



Always lay components on a clean, softcushioned surface during assembly.